

FIRE SAFETY CERTIFICATE

TO WHOM SO EVER IT MAY CONCERN

APPENDIX - L

FORM "S"

(SEE RULE 88 (5))

Fire Audit Report

Year 2023

To

WEST CENTRAL RAILWAY HIGH SCHOOL,
LOCO TALAIYA, SOUTH LINES, JABALPUR
MADHYA PRADESH PIN CODE-482001

Sir,

Sub: Submission of fire Certificate No.-**JBP/FSC/0092/2023**

Date of Issue – 15/12/2023

Date of Expiry – 14/02/2024

THIS CERTIFICATE IS ISSUED AS PER THE MADHYA PRADESH UADD BHOPAL LETTER NO. **981/895002/2022/18-3**
ON DATED 16.12.2022.

I AM **Nikhil Ranpuriya** have inspected your building / premises on 15TH DEC **2023** and checked all Fire Equipment's / installations and have completed .

The fire Audit of the said Building / premises of WEST CENTRAL RAILWAY HIGH SCHOOL,
JABALPUR Madhya Pradesh.

According to the use and character of occupancy; the campus includes building as "EDUCATION BUILDING"
Height for Building (4MTR) is Configurations of school is Ground floor only. So that it is falls under sub-
division (B-1)

Height of the building – 4 meter (approx.)

No. of floors – Ground

2. Details of fire system installed are as below:-

S.No.	Particular	Available/installed or not installed (as per requirements) (Give comments)	Comments for working of System (attach detail, if any)
1.	Access	Available	APPROCH ROAD OF 20 FEET MAIN ROAD
1.	Wet Riser	Not Required as per the NBC 2016 PART IV TABLE NO 7	
2.	Down Comer	Not Required as per the NBC 2016 PART IV TABLE NO 7	
3.	Hose Reel	Not Available	
4.	Automatic Sprinkler System	Not Required as per the NBC 2016 PART IV TABLE NO 7	
5.	Yard Hydrant	Not Required as per the NBC 2016 PART IV TABLE NO 7	
6.	Underground Tank with Draw off connection	Not Required as per the NBC 2016 PART IV TABLE NO 7	
7.	Terrace Tank	Available	5 KL
8.	Fire Pump	Not Required as per the NBC 2016 PART IV TABLE NO 7	
9.	Terrace Pump	Not Available	
10.	Fire Aid Fire Fighting Appliances	Available	AS PER IS 2190
11.	Pressurization System	Available	Naturally Ventilated
12.	Auto detection System	Not Required	
13.	Manual Operated Electrical Fire Alarm System	Not Required	
14.	P.A. System with talk back facility	Not Required as per the NBC 2016 PART IV TABLE NO 7	
15.	Emergency Light	Available	Connected With Inverter
16.	Auto D.G. Set	Not Required	
17.	Illuminated Exit Sign	Available	
18.	Means of Escape	Available	
19.	Compartmentation	Not Required as per the NBC 2016 PART IV TABLE NO 7	
20.	MCB/ELCB	Installed	
21.	Fireman Switch in Lift	Not Required	
22.	Hose Boxes with Delivery hose and Branches	Not Required as per the NBC 2016 PART IV TABLE NO 7	
23.	Refuge Area	Not Required as per the NBC 2016 PART IV TABLE NO 7	
24.	Any other installation	Not Available	

It is Conclude that the Building Fire Protection System work as above installed as per the NBC 2016 table no 7 and Indian standards, fire extinguishers are in Working Condition at the time of audit.

Note- Fire Hose reel system need to install within two months.

शर्तें

- (1) भवन अनुज्ञा में लिखित सभी शर्तों को मान्य करना अनिवार्य होगा।
- (2) भवन का स्थल निरीक्षण नियमानुसार द्वारा भवन कर्मचारी की उपस्थिति में उपकरणों को संचालित कराकर तैयार /संस्था के मैनेजर / किया गया है। मौका निरीक्षण रिपोर्ट में फिक्स फायरINSTALLATION भवन में स्थापित फस्ट फायर फाईटिंग व्यवस्था स्थल निरीक्षण के समय निर्धारित मापदण्ड अनुसार पाई गई है। जिसका स्पष्ट उल्लेख निरीक्षण प्रतिवेदन में किया गया है। निरीक्षण रिपोर्ट में उल्लेखित प्रावधान नेशनल बिल्डिंग कोड भाग 2016- फायर सेफ्टी के प्रावधानों अनुसार स्थापित किये गये है। जिसका निरीक्षण प्रतिवेदन में 04 विस्तृत उल्लेख किया गया है।
- (3) आवेदक को कार्यालय निरीक्षण रिपोर्ट में उल्लेखित प्रावधानों के साथ -साथ फायर सेफ्टी हेतु नेशनल बिल्डिंग कोड भाग 2016- 04 में निर्धारित अन्य आवश्यक प्रावधानों एवं निर्धारित आईएस मानकों का पालन करना अनिवार्य होगा। स्थल निरीक्षण में इन प्रावधानों का पालन न पाये जाने पर अग्नि प्राधिकारी को फायर सुरक्षा प्रमाण पत्र निरस्त करने का पूर्ण अधिकार होगा।
- (4) आवेदक को नियमानुसार स्थापित अग्निशमन उपकरणों का निर्धारित आईएस मानकों के अनुसार प्रावधानित समयसीमा में संधारण करना एवं संधारण हेतु आवश्यक अर्हताधारी कर्मचारी रखना अनिवार्य होगा।
- (5) दिनांक 30 जून से पहले प्रति वर्ष अग्नि सुरक्षा ऑडिट कराकर अग्नि विभाग में प्रस्तुत करना अनिवार्य होगा।
- (6) दिनांक 30 जून से पहले विद्युत सुरक्षा विभाग से प्रति वर्ष इलेक्ट्रिकल सेफ्टी ऑडिट करा कर समन्वित डिपार्टमेंट को प्रस्तुत करना होगा
- (7) भवन अनुज्ञा प्रमाण पत्र म.प. भूमि विकास नियम 2012 के अंतर्गत कोई भी त्रुटि पाए जाने पर समन्वित विभाग इस प्रमाण पत्र को तत्काल रूप से निरस्त करने का अधिकार होगा।
- (8) भविष्य में किसी भी प्रकार की आगजनी की अप्रिय घटना घटित होती है, तो इसके लिये स्वयं भवन स्वामी जिम्मेदार होंगे। अन्य कोई नहीं।

Name:-Nikhil Ranpuriya

Designation:-M.P.GovernmentAuthorizedFireConsultant/LeadAuditor

License No: -02/BFB/2021

Signature:-